



Sandford & Down

 CID6043 Opera **SANDFORD** Type: **Vandagraph Trade**
Sandford & Down 24 Pier Street, West Hoe, Plymouth, , PL1 3BT, UK
 Tel **01752266248** GBP Trade Price List Vandagraph (0009) 

Add Issue

Credit Credit Limit 0.00GBP



SRS69223

SRS Created : 29 Aug 2025

Created By Ryan Swaine

Add Watch

[Print Barcodes](#)

[Print A4 Sheet](#)

Split Items into Different SRS Numbers

[Edit Details](#)

Upload Document to SRS

Handle with care

Add Items to Supplier Returns Box



Add

☐ Return for Credit / Return to Stock
Unopened - will apply to all items on srs

☐ Clear From System - Force from System.
- will apply to all items on srs

Add notes to SRS

Add Notes

ADD DOCUMENT TO SRS : Document Description	Choose a file to upload: Choose file No file chosen
Next	

Next

Service Repair Sheet 69223		Notes
Company / Hospital	Sandford & Down	29/Aug/2025 Ryan Swaine
Contact Name	Dave	29/Aug/2025 Ryan Swaine
Department	Accounts	TEK-OX sn. TX2410. Failing to turn on, has replaced batteries, still not working.
Position		29/Aug/2025 Ryan Swaine
Company Phone	01752266248	Please pass to MG upon arrival
Direct Phone		08/Sep/2025 Robert Connor
Opera Account	SANDFORD	Received 1 x tek-ox s/n TX2410, with flow diverter, blue tee, and yellow case.
Email	dive@sandfordanddown.co.uk	
Order Number		
Viamed ORD Number		
Date Received Into building	08 Sep 2025	
Type	Quote Before Repair Move to Repair	
Issues?	376644	
Items for Repair		

...

SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN38147	Vandagraph Tek Ox	7910211	 967143	TX2410	Oxygen Analyser Tek-Ox	No	No	Complete - Repaired 30 Sep 2025 Michael Green	Intermittent power	00:45
SRN38147 Engineer Notes: INTERNAL NOTES not for customer discussion 30/Sep/2025 Michael Green The Tek-Ox analyser has been repaired. The case front and batteries have been replaced. The internal contacts have been cleaned.										

Currently Viewing ITEM SRN38147 Vandagraph Tek Ox 7910211 TX2410 Oxygen Analyser Tek-Ox

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	The Tek-Ox analyser has been repaired. The case front and batteries have been replaced. The internal contacts have been cleaned.	30/Sep/2025 Michael Green The Tek-Ox analyser has been repaired. The case front and batteries have been replaced. The internal contacts have been cleaned.	The Tek-Ox analyser has been repaired. The case front and batteries have been replaced. The internal contacts have been cleaned.

ISO REVIEW

Please Select

Instructions