

Service Repair Sheet SRS69259

Contact Name
Company/ Hospital Name
Department
Position
Direct Phone
General Phone
Opera Account
Email
Order Number
Date Received
Booked in By
Main Company
Type Return

Martin Hill
Royal Derby Hospital
Clinical Engineering

01332 788031
01332340131
00001390
martin.hill3@nhs.net

08/Oct/2025
Robert Connor
Viamed
Warranty

VIAMEDclean
Goods In Only
Decontamination
certificate provided
by customer

☒

Cleansed by Viamed,
if no declaration certificate
from customer
Signed: _____
Date: _____

☒

Goods Out Only
Cleansed by Viamed before
returning to customer
Signed: _____
Date: _____

Notes 07/Oct/2025 Sophie Lines
07/Oct/2025 Sophie Lines
Sending 2x sensors which customer says have failed out of the box - V108455 and V10452 - the warranty is valid until 14th October.
08/Oct/2025 Robert Connor
Received 2 x R-30v s/n V108452, V108455.

Ready For quote

Repair Complete Signed

CCgreen 10-10-25

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN38208	Oxygen Sensor	0110040	V108452	Yes
SRN38209	Oxygen Sensor	0110040	V108455	Yes

0140013 x 2 FOC
old S/N, SRS, SRN

0110040 x 2 FOC
new S/N, SRS, SRN

UPS x 1 FOC