

Service Repair Sheet 69261  
Contact Name Oskar Slechta  
Company/ Hospital Name Chromservis s.r.o  
Position Senior Internal Sales Advisor  
Direct Phone 420274021221  
General Phone 420274021211  
Opera Account 00012607  
Email o.slechta@chromservis.eu  
Date Received 14/Oct/2025  
Booked in By Robert Connor

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38224	0110122	278828	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110122

Replaced under warranty with S/N 287622.

---