

# Service Repair Sheet SRS69262

Contact Name

Laura Gardner

Company/ Hospital Name

Leidos Supply Ltd

Department

Position

Direct Phone

08009995533

General Phone

08009995533

Opera Account

00012918

Email

Laura.Gardner124@Teamleidos.r

Order Number

Date Received

21/Oct/2025

Booked in By

Robert Connor

Main Company

Viamed

Type Return

Quote

## VIAMEDclean

### Goods In Only

Decontamination  
certificate provided  
by customer

Cleaned by Viamed,  
if no declaration certificate  
from customer

Signed: RC

Date: 21/10/25

### Goods Out Only

Cleaned by Viamed before  
returning to customer

Signed: \_\_\_\_\_

Date: \_\_\_\_\_

Notes 09/Oct/2025 Kate Griffiths

09/Oct/2025 Kate Griffiths

would like to send in AX300 0111230 s/n: 332915. It is not picking up any readings. Batteries/sensor/cable all changed, still same issue. Their ref: Z279606. Asked for cert of decont/no batteries/SRS np. on all paperwork

21/Oct/2025 Robert Connor

Received 1 x AX300 s/n 332915, with 3 x AA battery, coiled cable s/n 0014792, R-17MED s/n 782241, with flow diverter and blue tee, and AX/MX stand with 2 suction cup feet.

Ready For quote

CGreen 31-10-25

Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN38227	Oxygen Monitor	0111230	332915	2
SRN38228	Misc. Cable	0131202	0014792	2
SRN38229	Oxygen Sensor	0110017	782241	2

0140050 x 1 FOC  
S/N, SRS, SRN NO fault

0140012 x 1  
S/N, SRS, SRN  
Faulty see line below

0110017 x 1 @ £54.40  
SRS, SRN.

0140025 x 1 FOC  
S/N, SRS, SRN NO fault

UPS x 1 FOC