

Service Repair Sheet 69270

| | |
|------------------------|------------------------------|
| Contact Name | Mick Jacobs |
| Company/ Hospital Name | Kent Diving Services |
| Direct Phone | 01474 247720 |
| General Phone | 01474 247720 |
| Opera Account | CID12049 |
| Email | kentdivingservices@gmail.com |
| Date Received | 21/Oct/2025 |
| Booked in By | Robert Connor |

| | | | | |
|----------|---------|------|------------------------|--|
| Repair | Ref | S/N | Equipment Type | |
| SRN38226 | 9710203 | 1199 | Oxygen Analyser TEK-OX | Complete - Repaired Time :1.5 Hour(s) |

The Tek-Ox analyser has been repaired. The battery contacts and wiring harness have been replaced. The R-17VAN Oxygen sensor has been replaced with SN:113896. New batteries have been fitted.
