Service Repair Sheet 69278

Contact Name Martin Hill

Company/ Hospital Name Royal Derby Hospital Department Clinical Engineering Direct Phone 01332 788031 General Phone 01332340131 Opera Account 00001390

Email martin.hill3@nhs.net

Date Received 27/Oct/2025 Booked in By Robert Connor

Repair Ref S/N Equipment Type Under Warranty

SRN38252 0110040 V108459 Oxygen Sensor

Time: 0 Hour(s)

Parts Replaced

Qty: 1 0110040

Replaced under warranty with S/N V108634.