

## Service Repair Sheet 69269

Contact Name	Jorge Santana
Company/ Hospital Name	East Surrey Hospital
Direct Phone	01737768511 x6044
General Phone	01737768511
Opera Account	00004300
Email	Jorge.Santana@nhs.net
Date Received	27/Oct/2025
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN38242	0110040	V107754	Oxygen Sensor	Return Unrepaired
				Time :0 Hour(s)

Out of warranty.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38243	0110040	V108204	Oxygen Sensor	
				Time :0 Hour(s)

Parts Replaced

Qty: 1 0110040

Replaced under warranty with S/N V108622.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38244	0110040	V108245	Oxygen Sensor	
				Time :0 Hour(s)

Parts Replaced

Qty: 1 0110040

Replaced under warranty with S/N V108623.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38245	0110040	V108341	Oxygen Sensor	
				Time :0 Hour(s)

Parts Replaced

Qty: 1 0110040

Replaced under warranty with S/N V108624.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38246	0110040	V108342	Oxygen Sensor	
				Time :0 Hour(s)

Parts Replaced

Qty: 1 0110040

Replaced under warranty with S/N V108625.

Service Repair Sheet 69269

Contact Name Jorge Santana  
 Company/ Hospital Name East Surrey Hospital  
 Direct Phone 01737768511 x6044  
 General Phone 01737768511  
 Opera Account 00004300  
 Email Jorge.Santana@nhs.net  
 Date Received 27/Oct/2025  
 Booked in By Robert Connor

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38247	0110040	V108345	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110040

Replaced under warranty with S/N V108626.

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38248	0110040	V108346	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110040

Replaced under warranty with S/N V108627.

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38249	0110040	V108530	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110040

Replaced under warranty with S/N V108641.

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38250	0110040	V108531	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110040

Replaced under warranty with S/N V108642.

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38251	0110040	V108533	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110040

Replaced under warranty with S/N V108645.

---

