

Service Repair Sheet SRS69269

Contact Name

Jorge Santana

Company/ Hospital Name

East Surrey Hospital

Department

Position

Direct Phone

01737768511 x6044

General Phone

01737768511

Opera Account

00004300

Email

Jorge.Santana@nhs.net

Order Number

Date Received

27/Oct/2025

Booked in By

Robert Connor

Main Company

Viamed

Type Return

Bring To Attention

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer

Cleaned by Viamed,
if no declaration certificate
from customer

Signed: _____

Date: _____

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____

Date: _____

Notes 17/Oct/2025 Ryan Swaine

17/Oct/2025 Ryan Swaine

10x R-30V sensors that have or a suspected of having the gas leak issue.

To replace with new sensors.

27/Oct/2025 Robert Connor

Received 10 x R-30v s/n V107754, V108204 (opened), V108245, V108341, V108342, V108345, V108346, V108530, V108531, V108533. None of the returned sensors belong to the batches with reported failures, one has been opened and reported as faulty.

Ready For quote

Repair Complete Signed

CGN 3.11.25 -

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN38242	Oxygen Sensor	0110040	V107754	N
SRN38243	Oxygen Sensor	0110040	V108204	Yes
SRN38244	Oxygen Sensor	0110040	V108245	Yes
SRN38245	Oxygen Sensor	0110040	V108341	Yes
SRN38246	Oxygen Sensor	0110040	V108342	Yes
SRN38247	Oxygen Sensor	0110040	V108345	Yes
SRN38248	Oxygen Sensor	0110040	V108346	Yes
SRN38249	Oxygen Sensor	0110040	V108530	Yes
SRN38250	Oxygen Sensor	0110040	V108531	Yes
SRN38251	Oxygen Sensor	0110040	V108533	Yes

0140013 x 9 FOC
S/N's, SRS, SRN's

0110040 x 9 FOC
New S/N's, SRS, SRN's

0140015 x 1
S/N, SRS, SRN
out of warranty.

UPS x 1 FOC