

2 490
p9-71
€ 13-37
11-50
115

Service Repair Sheet SRS69267

Contact Name
Company/ Hospital Name
Department
Position
Direct Phone
General Phone
Opera Account
Email
Order Number
Date Received
Booked in By
Main Company
Type Return

Marc Andre Dressel
Maria Hilf Hospital

02902 891550
02902891550
CID34903
Marc.Dressel@krankenhaus-wars

22/Oct/2025
Robert Connor
Viamed
Quote

VIAMEDclean

Goods In Only
Decontamination
certificate provided
by customer

Cleaned by Viamed,
if no declaration certificate
from customer

Signed: RS
Date: 22/10/25

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____
Date: _____

Notes Customer has a VM-2500-S (serial number 70340144) which is displaying 'device defective'. I have provided the SRS number and instructions for return. Please see their original email attached

22/Oct/2025 Robert Connor

Received 1 x VM-2500-S s/n 70340144, with silicone cover v 2, one part of bottom catch of battery door is detached, the other is almost detached. There is something small rattling around inside the device.

Sold to RKB

Ready For quote

CGreen 4-11-25

Repair Complete Signed

E. End
user
Proforma

New Customer

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN38231	Capnograph	4410520	70340144	N

44805

4440000 x 1 @ 0.5hr @ 70 per hr = €35

S/N, SRS, SRN

4480520 x 1 @ €165

SRS, SRN

4430201 x 1 @ €17.50

SRS, SRN

4430050 x 1 @ €3.30

ins

PP UPS x 1

32x24x14cm

1kg 0.70kg