

Service Repair Sheet 69196

Contact Name	Clay Harper
Company/ Hospital Name	Sage Services Group
Position	VP of Operations
Direct Phone	8772817243
General Phone	8432845844
Opera Account	00006727
Email	clay@sageservicesgroup.com
Date Received	16/Sep/2025
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN38172	1410000	PR01883A18	Foetal Simulator	Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1	1480000
Qty: 1	1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.
