Service Repair Sheet 69293

Contact Name
Company/ Hospital Name
Department
Direct Phone
General Phone
Opera Account

Nigel Baldwin
St Woolos Hospital
Medical Electronics
01633234234
01633234234
00003836

Email Nigel.baldwin@wales.nhs.uk

Date Received 25/Nov/2025 Booked in By Robert Connor

Repair Ref S/N Equipment Type Under Warranty

SRN38361 0014650 ESHK00895 Pulse Oximetery Finger Sensor Return Stock / Demo Stock

Time :0 Hour(s)

Parts Replaced

Qty: 1 0014651

Serviced by Q.A. by

Repair Report:

The 0014650 SpO2 sensor has been replaced with a 0014651 SMARTsat version SN:GJJ10085.