

Service Repair Sheet SRS69298

Contact Name
Company/ Hospital Name
Department
Position
Direct Phone
General Phone
Opera Account
Email
Order Number
Date Received
Booked in By
Main Company
Type Return

Sara Walsh
Gama Aviation Plc

Clinical Service Manager
01202013687
01252553029
CID19740
sara.walsh@gamaaviation.com

01/Dec/2025
Robert Connor
Viamed
Quote

VIAMEDclean

Goods In Only
Decontamination
certificate provided
by customer



Cleaned by Viamed,
if no declaration certificate
from customer

Signed: _____
Date: _____



Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____
Date: _____

Notes 24/Nov/2025 Kate Griffiths

24/Nov/2025 Kate Griffiths

MaxBlend 2 Performance check required. S/N: FA56833001. Asked for cert of decont/SRS on all paperwork/no batteries

01/Dec/2025 Robert Connor

Received 1 x MaxBlend2 s/n FA56833001, with blender nip, power supply, MAX-550E s/n HH82199025, with blender flow diverter and sensor cable.

Ready For quote

C Green 5.12.25

Repair Complete Signed _____

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN38455	Blender	0310291	FA56833001	M
SRN38456	Oxygen Sensor	0110452	HH82199025	N

last time we had
no stock of 0110454
but used 0110452
and re used their
flow diverter.

0380060 x 1 @ £92.40
S/N, SRS

0110454 x 1 @ £140.40
SRS, S/N

UPS x 1 £12.