

Service Repair Sheet SRS69262

Contact Name Laura Gardner
 Company/ Hospital Name Leidos Supply Ltd
 Department
 Position
 Direct Phone 08009995533
 General Phone 08009995533
 Opera Account 00012918
 Email Laura.Gardner124@Teamleidos.r
 Order Number
 Date Received 21/Oct/2025
 Booked in By Robert Connor
 Main Company Viamed
 Type Return Quote

VIAMEDclean	
Goods In Only	
Decontamination certificate provided by customer	
<input checked="" type="checkbox"/> Cleaned by Viamed, if no declaration certificate from customer Signed: <i>RC</i> Date: <u>21/10/25</u>	
Goods Out Only	
Cleaned by Viamed before returning to customer	
Signed: _____ Date: _____	

Notes 09/Oct/2025 Kate Griffiths

09/Oct/2025 Kate Griffiths

would like to send in AX300 0111230 s/n: 332915. It is not picking up any readings. Batteries/sensor/cable all changed, still same issue. Their ref: Z279606. Asked for cert of decont/no batteries/SRS np. on all paperwork

21/Oct/2025 Robert Connor

Received 1 x AX300 s/n 332915, with 3 x AA battery, coiled cable s/n 0014792, R-17MED s/n 782241, with flow diverter and blue tee, and AX/MX stand with 2 suction cup feet.

Ready For quote

CGreen 31-10-25

Repair Complete Signed

CGreen 19-12-25

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN38227	Oxygen Monitor	0111230	332915	N
SRN38228	Misc. Cable	0131202	0014792	N
SRN38229	Oxygen Sensor	0110017	782241	N

0140050 x 1 FOC
 S/N, SRS, SRN no fault

0140012 x 1
^{old}
 S/N, SRS, SRN
 Faulty see line below

0110017 x 1 @ £54.40
^{new}
 S/N SRS, SRN.

0140025 x 1 FOC
 S/N, SRS, SRN no fault

UPS x 1 FOC