

Service Repair Sheet 69262

Contact Name	Laura Gardner
Company/ Hospital Name	Leidos Supply Ltd
Direct Phone	08009995533
General Phone	08009995533
Opera Account	00012918
Email	Laura.Gardner124@Teamleidos.mod.uk
Order Number	Z279606/694036
Date Received	21/Oct/2025
Booked in By	Robert Connor

Repair Ref S/N Equipment Type
SRN38227 0111230 332915 Oxygen Monitor No Fault Found
Time :0 Hour(s)

The AX300 Oxygen analyser has been tested. No fault was found.

Repair	Ref	S/N	Equipment Type	
SRN38228	0131202	0014792	Misc. Cable	No Fault Found
				Time :0 Hour(s)

The Oxygen sensor cable has been tested. No fault was found.

Repair	Ref	S/N	Equipment Type	
SRN38229	0110017	782241	Oxygen Sensor	End Of Life
				Time :0 Hour(s)

Parts Replaced

The R-17MED Oxygen sensor has expired. A new R-17MED Oxygen sensor has been supplied SN:267743.