

Service Repair Sheet 69312
Contact Name David Watson
Company/ Hospital Name Darlington Memorial Hospital
Department Clinical Engineering Department
Position Clinical Engineering Technician
Direct Phone 01325743048
General Phone 01325380100
Opera Account 00001350
Email david.watson28@nhs.net
Order Number CDD0006492554
Date Received 15/Dec/2025
Booked in By Robert Connor

| Repair | Ref | S/N | Equipment Type | |
|----------------|---------|---------|----------------|--|
| SRN38474 | 0310030 | VMBC14 | Tom Thumb | Complete - Repaired Time :0 Hour(s) |
| Parts Replaced | | | | |
| | Qty: 1 | 0380000 | | |

Tom Thumb TT480 VMBC14 has been stripped and cleaned then reassembled with new O rings. The two valves have been checked and reset before QA.

| Repair | Ref | S/N | Equipment Type | |
|----------------|---------|---------|----------------|--|
| SRN38475 | 0310030 | VMBC19 | Tom Thumb | Complete - Repaired Time :0 Hour(s) |
| Parts Replaced | | | | |
| | Qty: 1 | 0380000 | | |

Tom Thumb TT480 VMBC19 has been stripped and cleaned then reassembled with new O rings. The two valves have been checked and reset before QA.

| Repair | Ref | S/N | Equipment Type | |
|----------------|---------|---------|----------------|--|
| SRN38476 | 0310030 | VMD113 | Tom Thumb | Complete - Repaired Time :0 Hour(s) |
| Parts Replaced | | | | |
| | Qty: 1 | 0380000 | | |

Tom Thumb TT480 VMD113 has been stripped and cleaned then reassembled with new O rings. The two valves have been checked and reset before QA.
