

Service Repair Sheet 69298

Contact Name Sara Walsh
Company/ Hospital Name Gama Aviation Plc
Position Clinical Service Manager
Direct Phone 01202013687
General Phone 01252553029
Opera Account CID19740
Email sara.walsh@gamaaviation.com
Order Number SRS69298
Date Received 01/Dec/2025
Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN38455	0310291	FA56833001	Blender	Complete - Repaired Time :0 Hour(s)

Parts Replaced
Qty: 1 0380060

The Maxblend 2 FA56833001 has been performance and calibration checked.

Repair	Ref	S/N	Equipment Type	
SRN38456	0110452	HH82199025	Oxygen Sensor	Complete - Repaired Time :0 Hour(s)

Parts Replaced
Qty: 1 0110454

Replacement sensor is S/N LJ38599083.
