

## Service Repair Sheet SRS69298

Contact Name  
 Company/ Hospital Name  
 Department  
 Position  
 Direct Phone  
 General Phone  
 Opera Account  
 Email  
 Order Number  
 Date Received  
 Booked in By  
 Main Company  
 Type Return

Sara Walsh  
 Gama Aviation Plc  
 Clinical Service Manager  
 01202013687  
 01252553029  
 CID19740  
 sara.walsh@gamaaviation.com  
 01/Dec/2025  
 Robert Connor  
 Viamed  
 Quote

<b>VIAMEDclean</b>	
<b>Goods In Only</b>	
Decontamination certificate provided by customer <input checked="" type="checkbox"/>	
Cleaned by Viamed, if no declaration certificate from customer	
Signed:	Date:
<input checked="" type="checkbox"/>	
<b>Goods Out Only</b>	
Cleaned by Viamed before returning to customer	
Signed:	Date:

Notes 24/Nov/2025 Kate Griffiths

24/Nov/2025 Kate Griffiths

MaxBlend 2 Performance check required. S/N: FA56833001. Asked for cert of decont/SRS on all paperwork/no batteries

01/Dec/2025 Robert Connor

Received 1 x MaxBlend2 s/n FA56833001, with blender nip, power supply, MAX-550E s/n HH82199025, with blender flow diverter and sensor cable.

Ready For quote

C Green 5.12.25

Repair Complete Signed

C Green 7.1.26

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN38455	Blender	0310291	FA56833001	M
SRN38456	Oxygen Sensor	0110452	HH82199025	N

last time we had  
 no stock of 610454  
 but used 010452  
 and re used their  
 flow diverter.

0380060 x 1 @ £92.40

S/N, SRS, SRN

0140012 x 1 FOC

old S/N, SRS, SRN

0110454 x 1 @ £140.40

S/N SRS, SRN

UPS x 1 £12.