

Service Repair Sheet 69342
Contact Name Donna Kelly
Company/ Hospital Name Bradford Royal Infirmary
Department Clinical Engineering
Position Helpdesk Team Leader
Direct Phone 01274364147
General Phone 01274542200
Opera Account 00000620
Email donna.kelly2@bthft.nhs.uk
Order Number 34527972
Date Received 27/Jan/2026
Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN38516	1410000	PR03485A10	Foetal Simulator	Complete - Repaired Time :0 Hour(s)

V1000 has had transducer interface cushion replaced and calibration has been checked.
