

# North Middlesex University Hospital

NHS Trust

North Middlesex University Hospital  
Clinical Engineering  
Main Building Floor Level [-1]  
Sterling Way, London N18 1QX  
Email: kamal.pacitti@nhs.net  
Tel: 020 88872582  
Date of dispatch: 28/01/2026  
Our WO#: 135694, 135692 & 133161

To: Viamed LTD,  
15 Station Road, Cross Hills,  
Keighley, BD20 7DT

Contact Name: Service Dept  
E-mail: kate.griffiths@viamed.co.uk  
Tel: 44 (0)1535 634 542

Dear..... Service Dept- SRS69349

Please find enclosed equipment X3 Blenders  
Serial No's: B1307013, B1307011 & BX1854175.

Please quote us for the cost of the repair by e-mail, so that we can provide you with an order number.

Fault description: X3 Blenders for overhauling/service.

**DECONTAMINATION (Please tick one)**

- A) This equipment is NOT as far as I am aware contaminated by any potentially infected material (eg. Blood/body fluids)
- B) The equipment may be contaminated by potentially infected material (eg. Blood/body fluids) and has been decontaminated externally, in accordance with the North Middlesex Hospital trust Policy.
- C) The equipment may be contaminated with potentially infected material (eg. Blood/body fluids) but could not be decontaminated.

**Contaminated/potentially hazardous equipment must be despatched in a sealed container/bag**

**TRANSPORT/COURIERS NAME:** FEDEX

PRINT: \_\_\_\_\_  
SIGN: \_\_\_\_\_  
DATE: \_\_\_\_\_