

Service Repair Sheet 69289

Contact Name Mr Mahesha
Company/ Hospital Name BDI India Private Limited
Department Customer Support
Position Customer Support
Direct Phone 918022560418
General Phone 918022560418
Opera Account 00006454
Email mahesha@bdi-india.com
Order Number SRS69289
Date Received 17/Nov/2025
Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN38354	1410000	PR03143A10	Foetal Simulator	Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1 1480000

Qty: 1 1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.

Repair	Ref	S/N	Equipment Type	
SRN38355	1410000	PR03143A11	Foetal Simulator	Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1 1480000

Qty: 1 1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.

Repair	Ref	S/N	Equipment Type	
SRN38356	1410000	PR03143A14	Foetal Simulator	Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1 1480000

Qty: 1 1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.
