

Service Repair Sheet 69335
Contact Name David Watson
Company/ Hospital Name Darlington Memorial Hospital
Department Clinical Engineering Department
Position Clinical Engineering Technician
Direct Phone 01325743048
General Phone 01325380100
Opera Account 00001350
Email david.watson28@nhs.net
Order Number RXP0006518641
Date Received 19/Jan/2026
Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN38506	0310030	VMBC17	Tom Thumb	Complete - Repaired Time :0 Hour(s)
Parts Replaced				
	Qty: 1	0380000		

Tom Thumb TT480 VMBC17 has been stripped and cleaned then reassembled with new O rings. The two valves have been checked and reset before QA.

Repair	Ref	S/N	Equipment Type	
SRN38507	0310030	VMDI 11	Tom Thumb	Complete - Repaired Time :0 Hour(s)
Parts Replaced				
	Qty: 1	0380000		

Tom Thumb TT480 VMDI11 has been stripped and cleaned then reassembled with new O rings. The two valves have been checked and reset before QA.

Repair	Ref	S/N	Equipment Type	
SRN38508	0310030	VMD114	Tom Thumb	Complete - Repaired Time :0 Hour(s)
Parts Replaced				
	Qty: 1	0380000		

Tom Thumb TT480 VMD114 has been stripped and cleaned then reassembled with new O rings. The two valves have been checked and reset before QA.
