

Service Repair Sheet SRS69281

Contact Name  
Company/ Hospital Name  
Department  
Position  
Direct Phone  
General Phone  
Opera Account  
Email  
Order Number  
Date Received  
Booked in By  
Main Company  
Type Return

Hanson Lijing  
Lifemed Medical Supplies

+86 13603093265  
852 27108200  
00006005  
info@lifemed.cn

02/Dec/2025  
Robert Connor  
Viamed  
Warranty

<b>VIAMEDclean</b>	
<b>Goods In Only</b>	
Decontamination certificate provided by customer	<input type="checkbox"/>
Cleaned by Viamed, if no declaration certificate from customer	<input type="checkbox"/>
Signed: _____	
Date: _____	
<b>Goods Out Only</b>	
Cleaned by Viamed before returning to customer	
Signed: _____	
Date: _____	

Notes 27/Oct/2025 Aqib Majeed

27/Oct/2025 Aqib Majeed

Customer is bringing 4 sensors to Medica and handing them over to Ryan, SN: 219380, 261113, 261145 and 244375, all are still under warranty.

SN:26113 & 261145 have a low Voltage reading, SN:219380 has a leakage and 244375 tested reading below standard in first use.

02/Dec/2025 Robert Connor

Received 4 x UFO 130-2 s/n 219380, 244375, 261113, 261145.

Ship with next order.

Ready For quote

Repair Complete Signed

CCNORR 10.2.26

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN38459	Oxygen Sensor	0110081	219380	Yes
SRN38460	Oxygen Sensor	0110081	244375	Yes
SRN38461	Oxygen Sensor	0110081	261113	Yes
SRN38462	Oxygen Sensor	0110081	261145	Yes

0140013 x 4 @ FOC  
old S/N, SRS, SRN

0110081 x 4 FOC  
new S/N, SRS, SRN

UPS x 1 <sup>FOC</sup> - ship with next order