

Service Repair Sheet 69281

Contact Name Hanson Lijing  
Company/ Hospital Name Lifemed Medical Supplies  
Direct Phone +86 13603093265  
General Phone 852 27108200  
Opera Account 00006005  
Email info@lifemed.cn  
Date Received 02/Dec/2025  
Booked in By Robert Connor

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38459	0110081	219380	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced under warranty with S/N 297020.

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38460	0110081	244375	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced under warranty with S/N 297021.

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38461	0110081	261113	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced under warranty with S/N 297022.

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38462	0110081	261145	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced under warranty with S/N 297025.

---