

Contacts

home

crm

employee

iso

meetings

opera

products

returns

sales

stock

stockbook

HOST Vandagraph's Contact Record For:

John Patten

CID35919 Opera CID35919 Type:

John Patten 23 Cleveland Drive, , Little Sutton, Ellesmere Port, , CH66 4XY, United Kingdom
Tel **07812910144** GBP Retail Price List Vandagraph (0010)

Home
 Details
 Memos
 Sales
 Stock Refs

Returns
 Service
 Distributors
 Documents
 Issues
 Regulatory
 Performance

SRS69351

SRS Created : 28 Jan 2026
Created By Sophie Lines
[Add Watch](#)

- [Print Barcodes](#)
- [Print A4 Sheet](#)
- [Split Items into Different SRS Numbers](#)
- [Edit Details](#)

Upload Document to SRS

ADD DOCUMENT TO SRS : Document Description	Choose a file to upload: <input type="button" value="Choose file"/> No file chosen
<input type="button" value="Next"/>	

Handle with care
Add Items to Supplier Returns Box

Return for Credit / Return to Stock Unopened - will apply to all items on srs

Clear From System - Force from System. - will apply to all items on srs

Add notes to SRS

Service Repair Sheet 69351		Notes
Company / Hospital	John Patten	28/Jan/2026 Sophie Lines 28/Jan/2026 Sophie Lines Customer ordered incorrect part number 0110225 R-22DEM on VANWEB2860. Wants to return and replace with 0110224 R-33DE. Once return received, Mike will send the sensor the customer wants and charge the extra £11 02/Feb/2026 Robert Connor Received 1 x R22DEM s/n S115026
Contact Name	John Patten	
Department		
Position		
Company Phone	07812910144	
Direct Phone		
Opera Account	CID35919	
Email	johnr_patten@hotmail.com	
Order Number		
Viamed ORD Number		
Date Received Into building	02 Feb 2026	
Issues?		

Items for Repair

SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN38521	Oxygen Sensor Vandagraph	0110225	2812715	S115026		Yes	No	Unfinished		00:00

Currently Viewing ITEM SRN38521 Oxygen Sensor Vandagraph 0110225 S115026

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	Non Supplied	Non added Yet	Non added Yet

↓

ISO REVIEW

Please Select

Instructions
