

Service Repair Sheet 69353

Contact Name Karen Carvell  
Company/ Hospital Name London Bridge Hospital  
Position UK HCA Site Administrator  
Direct Phone 07977700502  
General Phone 02035539022  
Opera Account 00003004  
Email karen.carvell@ergeagroup.com  
Date Received 11/Feb/2026  
Booked in By Robert Connor

---

| Repair   | Ref     | S/N    | Equipment Type | Serviced        |
|----------|---------|--------|----------------|-----------------|
| SRN38536 | 0111237 | 267366 | Oxygen Monitor | Time :0 Hour(s) |

Parts Replaced  
Qty: 1 0180005

The MX300 Oxygen monitor has been serviced. The unit is working as expected.

---

| Repair   | Ref     | S/N    | Equipment Type | Serviced        |
|----------|---------|--------|----------------|-----------------|
| SRN38537 | 0111237 | 267368 | Oxygen Monitor | Time :0 Hour(s) |

Parts Replaced  
Qty: 1 0180005

The MX300 Oxygen monitor has been serviced. The unit is working as expected.

---

| Repair   | Ref     | S/N     | Equipment Type | No Fault Found  |
|----------|---------|---------|----------------|-----------------|
| SRN38538 | 0131202 | 0001947 | Misc. Cable    | Time :0 Hour(s) |

The Oxygen sensor cable has been tested. No fault was found.

---

| Repair   | Ref     | S/N     | Equipment Type | No Fault Found  |
|----------|---------|---------|----------------|-----------------|
| SRN38539 | 0131202 | 0003874 | Misc. Cable    | Time :0 Hour(s) |

The Oxygen sensor cable has been tested. No fault was found.

---

| Repair   | Ref     | S/N     | Equipment Type | End Of Life     |
|----------|---------|---------|----------------|-----------------|
| SRN38540 | 0110018 | V100657 | Oxygen Sensor  | Time :0 Hour(s) |

Parts Replaced  
Qty: 1 0110018

The R-17V Oxygen sensor has been replaced with SN:V101169.

---

