

Service Repair Sheet 69364
Contact Name Artwell Bere
Company/ Hospital Name Blackpool Victoria Hospital
Position Medical Engineer
Direct Phone 01253957799
General Phone 01253 953120
Opera Account 00000571
Email artwell.bere@bfwml.co.uk
Order Number BA15029
Date Received 11/Feb/2026
Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN38535	1410000	PR02676A12	Foetal Simulator	Complete - Repaired Time :0 Hour(s)
Parts Replaced				
		Qty: 1	1480000	
		Qty: 1	1430309	

V1000 has had transducer interface cushion replaced and calibration has been checked.
