Gmail

Search mail

2 of 2

PACITTI, Kamal kaur (ROYAL FREE LONDON NHS FOUNDATION TRUST) 08:37 (4 hours ago)

to Kate, Steve

Good morning Kate,

I have a blender that was serviced by yourselves in Jan 2025. The serial number is BX1854180. It is showing the correct O2 concentration at 21% and 100%, but v tested at 40 and 60% it is showing ~100%. Is there anything I can try here to fix the issue or does it need to go back to yourselves for repair?

Thank You
&
Kind Regards

Kamal Pacitti (she/her)
Specialist Clinical Engineer

North Middlesex Hospital part of **Royal Free London NHS Foundation Trust**
| Sterling Way |
Clinical Engineering Department | Main building, level -1
London N18 1QX
Direct line: 020 8887 3790| e: kamal.pacitti@nhs.net |
www.northmid.nhs.uk

Follow us on Twitter @NorthMidNHS

Order confirmation