

Service Repair Sheet 69365
Contact Name Megan Osgood
Company/ Hospital Name North Cumbria University Hospitals NHS Trust
Department Medical Engineering
Position Medical Engineering Administration Support
Direct Phone 01228814672
General Phone 01228523444
Opera Account 00000980
Email Megan.Osgood@ncic.nhs.uk
Order Number RNNN400309106
Date Received 17/Feb/2026
Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN38542	1410000	PR01225A15	Foetal Simulator	Complete - Repaired Time :0 Hour(s)
Parts Replaced				
		Qty: 1	1480000	
		Qty: 1	1430309	

V1000 has had transducer interface cushion replaced and calibration has been checked.
