

Ryan Swaine Required Reading 5 Issues 2 Unread 2 ISO Tasks | My Requests 20.40 °C












Contacts »




HOST  Vandagraph's Contact Record For:

## Bavaria Blue for Safari

 CID9556 Opera **BAVARIA** Type: **Vandagraph Trade**

**Bavaria Blue for Safari** 3 Royal Mews, Chilwell, Nottingham, , NG9 5FZ, UK

Tel **0115 9431430** GBP Trade Price List Vandagraph (0009)

 Log Call  Add Issue

Proforma Credit Limit 0.00GBP

-  Home
 Details
 Memos
 Sales
 Stock Refs
-  Returns
 Service
 Distributors
 Documents
 Issues
 Regulatory

# SRS69280

SRS Created : 23 Oct 2025

Created By Ryan Swaine

[Add Watch](#)

[Print Barcodes](#)

[Print A4 Sheet](#)

[Split Items into Different SRS Numbers](#)

[Edit Details](#)

### Upload Document to SRS

ADD DOCUMENT TO SRS : Document Description	Choose a file to upload: <input type="button" value="Choose file"/> No file chosen

Handle with care

Add Items to Supplier Returns Box

Return for Credit / Return to Stock

Unopened - will apply to all items on srs

Clear From System - Force from System. - will apply to all items on srs

Add notes to SRS

### Service Repair Sheet 69280

Company / Hospital	Bavaria Blue for Safari
Contact Name	Paul Cooper
Department	
Position	
Company Phone	0115 9431430
Direct Phone	0115 943 1430
Opera Account	BAVARIA
Email	pscroyal@outlook.com
Order Number	
Viamed ORD Number	
Date Received Into building	27 Oct 2025
Type	<b>Repair Approved</b>
Issues?	381893

#### Notes

23/Oct/2025 Ryan Swaine

23/Oct/2025 Ryan Swaine

TEK-OX sn. TX3600. Burning batteries and may need a new power switch.

Please pass to MG on arrival

27/Oct/2025 Robert Connor

Received 1 x tek-ox s/n TX3600 14/Nov/2025 Catherine Spence Engineer

11/Dec/2025 Catherine Spence

Vandagraph Room

02/Jan/2026 Catherine Spence

in Vandagraph Room

#### LINKED ISSUE NOTES:

**381893:**

AutoGenerated Issue SRS69280 Appears to be Complete

**11 Dec 2025 Catherine Spence**

still with vandagraph Done

### Items for Repair

...

SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
<a href="#">SRN38268</a>	Vandagraph Tek Ox	7910201	 1848326	TX3600	Oxygen Analyser Tek-Ox + Quick-Ox	Yes	No	No Fault Found 26 Nov 2025 Michael Green	No Fault Found	00:00

SRN38268 Engineer Notes: **INTERNAL NOTES not for customer discussion**  
 26/Nov/2025 Michael Green  
 The Tek-Ox analyser has been tested. New batteries were installed and tested after being installed for a week. The batteries dropped in voltage from 1.528V to 1.527V. The test was repeated after 2 weeks. The voltage drop was to 1.526V.

26/Nov/2025 Michael Green  
 The described fault could not be reproduced. The battery door contact showed some marking and has been replaced, this could not account for the fault. New batteries have been installed.

**Currently Viewing ITEM SRN38268 Vandagraph Tek Ox 7910201 TX3600 Oxygen Analyser Tek-Ox + Quick-Ox**

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	The Tek-Ox analyser has been tested. The described fault could not be reproduced. The battery door contact showed some marking and has been replaced. New batteries have been installed.	<p>26/Nov/2025 Michael Green                      The Tek-Ox analyser has been installed and tested after being installed for a week. The batteries dropped in voltage from 1.528V to 1.527V. The test was repeated after 2 weeks. The voltage drop was to 1.526V.</p> <p>26/Nov/2025 Michael Green                      The described fault could not be reproduced. The battery door contact showed some marking and has been replaced, this could not account for the fault. New batteries have been installed.</p>	The Tek-Ox analyser has been tested. The described fault could not be reproduced. The battery door contact showed some marking and has been replaced. New batteries have been installed.

ISO REVIEW

Please Select

Instructions