


  
**Ryan Swaine** [Required Reading](#) 5 Issues **2 Unread** 2 ISO Tasks | [My Requests](#) 20.40 °C

Contacts   »  



HOST  Vandagraph's Contact Record For:

## Bavaria Blue for Safari

 CID9556 Opera **BAVARIA** Type: **Vandagraph Trade**  
**Bavaria Blue for Safari** 3 Royal Mews, Chilwell, Nottingham, , NG9 5FZ, UK  
 Tel **0115 9431430** GBP Trade Price List Vandagraph (0009) Log Call Add Issue  
 Proforma Credit Limit 0.00GBP

- Home
Details
Memos
Sales
Stock Refs
  
Returns
Service
Distributors
Documents
Issues
Regulatory

# SRS69369

SRS Created : 17 Feb 2026  
 Created By Ryan Swaine  
 Add Watch

- [Print Barcodes](#)
- [Print A4 Sheet](#)
- [Split Items into Different SRS Numbers](#)
- [Edit Details](#)

Handle with care

Add Items to Supplier Returns Box

Add

- Return for Credit / Return to Stock  
Unopened - will apply to all items on srs
- Clear From System - Force from System. -  
will apply to all items on srs

### Upload Document to SRS

ADD DOCUMENT TO SRS : Document Description	Choose a file to upload: <span style="border: 1px solid #ccc; padding: 2px;">Choose file</span> No file chosen <div style="border: 1px solid #ccc; height: 20px; width: 100%;"></div>
<span style="border: 1px solid #ccc; padding: 2px;">Next</span>	

Add notes to SRS

Add Notes

Service Repair Sheet 69369		Notes
Company / Hospital	Bavaria Blue for Safari	17/Feb/2026 Ryan Swaine
Contact Name	Paul Cooper	17/Feb/2026 Ryan Swaine
Department		VN202, at the edge of calibration, sometimes errors.
Position		Please pass to MG
Company Phone	0115 9431430	23/Feb/2026 Robert Connor
Direct Phone	0115 943 1430	Received 1 x VN202 s/n 03824, with 2 x AA battery and mounting plate.
Opera Account	BAVARIA	
Email	pscroyal@outlook.com	
Order Number		
Viamed ORD Number		
Date Received Into building	23 Feb 2026	
Type	<b>Warranty</b>	
Issues?		

### Items for Repair

...

SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)

<a href="#">SRN38551</a>	Oxygen Analyser VN202	7910110	 2658521	3824	VN202mkII - Manual Switch Off	Yes	No	Unfinished		00:00
--------------------------	-----------------------------	---------	--	------	-------------------------------------	-----	----	------------	--	-------

**Currently Viewing ITEM SRN38551 Oxygen Analyser VN202 7910110 3824 VN202mkII - Manual Switch Off**

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	Non Supplied	Non added Yet	Non added Yet

-

ISO REVIEW

Please Select

Instructions