

4-14
North Middlesex University Hospital



NHS Trust

North Middlesex University Hospital

Clinical Engineering

Main Building Floor Level [-1]

Sterling Way, London N18 1QX

Email: kamal.pacitti@nhs.net

Tel: 020 88872582

Date of dispatch: 28/02/2026

Our WO#: 128994

To: Viamed LTD,
15 Station Road, Cross Hills,
Keighley, BD20 7DT

Contact Name: Service Dept

E-mail: kate.griffiths@viamed.co.uk

Tel: 44 (0)1535 634 542

Dear..... Service Dept- SRS69377

Please find enclosed equipment Blender

Serial No's: BX1854180

Please quote us for the cost of the repair by e-mail, so that we can provide you with an order number.

Fault description: Blender not giving correct O2 concentration in the middle ranges.
Only giving correct readings at 21 and 100%.

DECONTAMINATION (Please tick one)

- A) This equipment is NOT as far as I am aware contaminated by any potentially infected material (eg. Blood/body fluids)
- B) The equipment may be contaminated by potentially infected material (eg. Blood/body fluids) and has been decontaminated externally, in accordance with the North Middlesex Hospital trust Policy.
- C) The equipment may be contaminated with potentially infected material (eg. Blood/body fluids) but could not be decontaminated.

Contaminated/potentially hazardous equipment must be despatched in a sealed container/bag

TRANSPORT/COURIERS NAME: FEDEX

PRINT: _____

SIGN: _____

DATE: _____