

Service Repair Sheet SRS69377

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Kamal Pacitti

North Middlesex University Hospital

Clinical Engineering Department

Specialist Clinical Engineer

02088873790

02088872000

00003070

kamal.pacitti@nhs.net

02/Mar/2026

Robert Connor

Viamed

Quote

VIAMEDclean

Goods In Only

Decontamination certificate provided by customer

Cleaned by Viamed, if no declaration certificate from customer

Signed: _____
Date: _____

Goods Out Only

Cleaned by Viamed before returning to customer

Signed: _____
Date: _____

Notes 25/Feb/2026 Kate Griffiths

25/Feb/2026 Kate Griffiths

Kamal has a faulty blender, s/n: BX1854180, "serviced by us in Jan 2025. It is showing the correct oxygen concentration at 21% and 100%, but when tested at 40 and 60% it is showing - 100%" SN advised that it should sent in.

26/Feb/2026 Kate Griffiths

UPDATE: they have used Fedex, tracking no. 889096728509

02/Mar/2026 Robert Connor

Received 1 x blender s/n BX1854180

Ready For quote

CGNEEN 5-3-26

Repair Complete Signed _____

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN38558	Blender	0310200	BX1854180	N

9940000 - 0.5hr £47.50

S/N, SRS, SRN

UPS x 1 @ £12.