

Service Repair Sheet 69379

Contact Name Katy Romanowski
Company/ Hospital Name Tenacore LLC
Position Director of Operations
Direct Phone 8002972241
General Phone 8002972241
Opera Account 00007996
Email Katy.Romanowski@tenacore.com
Date Received 04/Mar/2026
Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN38567	1410000	PR01807A10	Foetal Simulator	Complete - Repaired Time :0 Hour(s)
Parts Replaced				
		Qty: 1	1480000	
		Qty: 1	1430309	

V1000 has had transducer interface cushion replaced and calibration has been checked.
