

Service Repair Sheet 69377

Contact Name Kamal Pacitti
Company/ Hospital Name North Middlesex University Hospital
Department Clinical Engineering Department
Position Specialist Clinical Engineer
Direct Phone 02088873790
General Phone 02088872000
Opera Account 00003070
Email kamal.pacitti@nhs.net
Order Number RFL698554
Date Received 02/Mar/2026
Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN38558	0310200	BX1854180	Blender	Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 0.5 9940000

The fault was the blender readings went way out when the air pressure was reduced just a little.

The fault was traced to the rear balance block, one of the valves was sticking open due to a tiny speck of dirt. The block has been thoroughly cleaned and the ball replaced as a precaution.

After QA the blender BX1854180 now passes all tests as per the manual.
