

Service Repair Sheet SRS69377

Contact Name: Kamal Pacitti
 Company/ Hospital Name: North Middlesex University Hospital
 Department: Clinical Engineering Department
 Position: Specialist Clinical Engineer
 Direct Phone: 02088873790
 General Phone: 02088872000
 Opera Account: 00003070
 Email: kamal.pacitti@nhs.net
 Order Number:
 Date Received: 02/Mar/2026
 Booked in By: Robert Connor
 Main Company: Viamed
 Type Return: Quote

VIAMEDclean	
Goods In Only	
Decontamination certificate provided by customer	<input checked="" type="checkbox"/>
Cleaned by Viamed, if no declaration certificate from customer	<input checked="" type="checkbox"/>
Signed: _____	
Date: _____	
Goods Out Only	
Cleaned by Viamed before returning to customer	
Signed: _____	
Date: _____	

Notes 25/Feb/2026 Kate Griffiths

25/Feb/2026 Kate Griffiths

Kamal has a faulty blender, s/n: BX1854180, serviced by us in Jan 2025. It is showing the correct oxygen concentration at 21% and 100%, but when tested at 40 and 60% it is showing - 100% SN advised that it should sent in.

26/Feb/2026 Kate Griffiths

UPDATE: they have used Fedex, tracking no. 889096728509

02/Mar/2026 Robert Connor

Received 1 x blender s/n BX1854180

Ready For quote

CGNEEN 5.3.26

Repair Complete Signed

CGNEEN 16.3.26

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN38558	Blender	0310200	BX1854180	N

9940000 . 0.5hr £47.50

S/N, SRS, SRN

UPS x 1 @ £12.