

Service Repair Sheet 69387

Contact Name David Watson
Company/ Hospital Name Darlington Memorial Hospital
Department Clinical Engineering Department
Position Clinical Engineering Technician
Direct Phone 01325743048
General Phone 01325380100
Opera Account 00001350
Email david.watson28@nhs.net
Order Number CDD0006558559
Date Received 12/Mar/2026
Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN38587	0310030	VMD107	Tom Thumb	Complete - Repaired Time :0 Hour(s)
Parts Replaced				
	Qty: 1	0380000		

Tom Thumb TT480 VMD107 has been stripped and cleaned then reassembled with new O rings. The two valves have been checked and reset before QA.

Repair	Ref	S/N	Equipment Type	
SRN38588	0310030	VMDI12	Tom Thumb	Complete - Repaired Time :0 Hour(s)
Parts Replaced				
	Qty: 1	0380000		

Tom Thumb TT480 VMDI12 has been stripped and cleaned then reassembled with new O rings. The two valves have been checked and reset before QA.

Repair	Ref	S/N	Equipment Type	
SRN38589	0310030	VMBC15	Tom Thumb	Complete - Repaired Time :0 Hour(s)
Parts Replaced				
	Qty: 1	0380000		

Tom Thumb TT480 VMBC15 has been stripped and cleaned then reassembled with new O rings. The two valves have been checked and reset before QA.
