

Service Repair Sheet 69386

Contact Name Marino D`Aliessio
Company/ Hospital Name King George Hospital
Department Clinical Engineering
Position Acting Head
Direct Phone 02089705725
General Phone 02089838000
Opera Account 00002294
Email marino.daliessio@nhs.net
Order Number 70042204
Date Received 09/Mar/2026
Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN38571	1410000	PR03731A10	Foetal Simulator	Complete - Repaired Time :0 Hour(s)
Parts Replaced				
		Qty: 1	1480000	
		Qty: 1	1430309	

V1000 has had transducer interface cushion replaced and calibration has been checked.
