

Service Repair Sheet SRS69301

Contact Name Adam Wigfield
 Company/ Hospital Name Inspiration Healthcare Ltd
 Department
 Position
 Direct Phone
 General Phone 03301750000
 Opera Account 00012240
 Email
 Order Number
 Date Received 19/Mar/2026
 Booked in By Robert Connor
 Main Company Viamed
 Type Return Bring To Attention

VIAMEDclean	
Goods In Only Decontamination certificate provided by customer	<input type="checkbox"/>
Cleaned by Viamed, if no declaration certificate from customer	<input type="checkbox"/>
Signed: _____	
Date: _____	
Goods Out Only Cleaned by Viamed before returning to customer	
Signed: _____	
Date: _____	

Notes They have been informed by their customer that 1 x R-22MEDV 0110021 s/n V121884 failed out of box, the sensor is at 0V no matter the actual Ox concentration.
 25/Nov/2025 Kate Griffiths
 They have been informed by their customer that 1 x R-22MEDV 0110021 s/n V121884 failed out of box, the sensor is at 0V no matter the actual Ox concentration.
 19/Mar/2026 Robert Connor
 Received 1 x R22MEDV s/n V121884.

Ready For quote CGreen 19.3.26 GBP Distri.
 Repair Complete Signed CGreen 26.3.26 OK to keep as warranty as agreed with SN. Cg 26.3.26

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN38673	Oxygen Sensor	0110021	V121884	N

0140012 x 1 FOC
 old S/n, SRS, SRN

0110021 x 1 FOC E34
 SRS 69301, SRN 38673

↑ new S/N

~~UPS x 1~~ £12 UPS EXW FOC