

Service Repair Sheet 69325
Contact Name Ladee Villacorta
Company/ Hospital Name Respicare Enterprises Inc
Department Importation Department
General Phone 63288971187
Opera Account 00006710
Email imports@respicare.ph
Date Received 16/Mar/2026
Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN38592	1410000	PR02894A12	Foetal Simulator	Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1	1480000
Qty: 1	1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.
