

Service Repair Sheet 69403

Contact Name David Thomas
Company/ Hospital Name MDS Medical Limited
Direct Phone 01536 401607
General Phone 015364017607
Opera Account 00013117
Email david.thomas@mdsmedical.co.uk
Date Received 07/Apr/2026
Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38707	0111265	KK52911008	Oxygen Analyser	Complete - Repaired Time :0 Hour(s)

On inspection it was found that there has been some battery leakage causing a little corrosion to the battery contact.

After cleaning everything carefully the analyser is working again.

I have soak tested the analyser for a few days and it is working well again.
