

Service Repair Sheet SRS69403

Contact Name David Thomas  
 Company/ Hospital Name MDS Medical Limited  
 Department  
 Position  
 Direct Phone 01536 401607  
 General Phone 015364017607  
 Opera Account 00013117  
 Email david.thomas@mdsmedical.co.uk  
 Order Number  
 Date Received 07/Apr/2026  
 Booked in By Robert Connor  
 Main Company Viamed  
 Type Return Warranty

<b>VIAMEDclean</b>	
<b>Goods In Only</b> Decontamination certificate provided by customer	<input type="checkbox"/>
Cleaned by Viamed, if no declaration certificate from customer	<input checked="" type="checkbox"/>
Signed: <u>RC</u>	
Date: <u>7/4/26</u>	
<b>Goods Out Only</b> Cleaned by Viamed before returning to customer	
Signed: _____	
Date: _____	

Notes 02/Apr/2026 Steve Nixon  
 02/Apr/2026 Steve Nixon  
 Returning 1 x UltraMax. Was using up batteries very quickly and now will not switch on. Should still be covered under warranty, he says purchased in December.  
 02/Apr/2026 Kate Griffiths  
 s/n: KK52911008  
 07/Apr/2026 Robert Connor  
 Received 1 x ultramax s/n KK52911008, with blue silicone cover.

Ready For quote \_\_\_\_\_

Repair Complete Signed CCONNOR 14.4.26

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN38707	Oxygen Analyser	0111265	KK52911008	Yes

0140000 x 1 FOC  
 S/n, SRS, SRS

UPS x 1 @ £0.