

Service Repair Sheet SRS69411

Contact Name
Company/ Hospital Name
Department
Position
Direct Phone
General Phone
Opera Account
Email
Order Number
Date Received
Booked in By
Main Company
Type Return

Adam Wharton
North Cumbria University Hospital
EBME

01228814671
01228523444
00000980
adam.wharton@ncic.nhs.uk

23/Apr/2026
Robert Connor
Viamed
Quote

VIAMEDclean

Goods In Only

Decontamination certificate provided by customer

Cleaned by Viamed, if no declaration certificate from customer

Signed: RC
Date: 23/4/26

Goods Out Only

Cleaned by Viamed before returning to customer

Signed: _____
Date: _____

Notes 20/Apr/2026 Aqib Majeed

20/Apr/2026 Aqib Majeed

They have a v1000 device SN: PR01225A15 which appears to be no longer emitting a signal, they have replaced batteries but still not resolved.

23/Apr/2026 Robert Connor

Received 1 x V1000 s/n PR01225A15, with 4 x AA battery and blue fabric carry case.

Out of warranty, changed to quote.

Please remind customer that a declaration of decontamination status is required, and that sending paperwork with a repair will help identify incoming parcels and ensure their repairs are dealt with in a timely manner.

Ready For quote

CGNEEN 27.4.26

Repair Complete Signed _____

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN38749	Foetal Simulator	1410000	PR01225A15	N

1440000 x 1 @ 0.5hr. @ £95 per hr = £47.50.
S/N SRS, SRN
1430300 x 1 @ £97.50
~~S/N~~, SRS, SRN

UPS x 1 @ £12.
~~14400~~