

Need cost from
SINixon for a
part, messaged
him, CG 27.4.26

Service Repair Sheet SRS69404

Contact Name Mr Mahesh Shetty
 Company/ Hospital Name BDI India Private Limited
 Department Customer Support
 Position Sr. Professional Customer Support
 Direct Phone 918022560418
 General Phone 918022560418
 Opera Account 00006454
 Email mahasha@bdi-india.com
 Order Number
 Date Received 20/Apr/2026
 Booked in By Robert Connor
 Main Company Viamed
 Type Return Quote

VIAMEDclean	
Goods In Only	
Decontamination certificate provided by customer	<input type="checkbox"/>
Cleaned by Viamed, if no declaration certificate from customer	<input type="checkbox"/>
Signed: _____	
Date: _____	
Goods Out Only	
Cleaned by Viamed before returning to customer	
Signed: _____	
Date: _____	

Notes Customer would like to send in 10 x V1000 for calibration as usual. Some devices have missing parts, see their list in attached email please. The s/n are as follows: PR02540A13, PR02540A14, PR02529A20, PR02529A17, PR02529A22, PR02529A14, PR02380A12, PR02529A15, PR02529A18 and PR02529A11. I will mention that we need the devices to be cleaned or they will be charged a fee. They have not taken any notice of this in the past and always pay that fee. Will ask for cert of decontamination and no batteries and SRS number on all paperwork
 10/Apr/2026 Kate Griffiths

Customer would like to send in 10 x V1000 for calibration as usual. Some devices have missing parts, see their list in attached email please. The s/n are as follows: PR02540A13, PR02540A14, PR02529A20, PR02529A17, PR02529A22, PR02529A14, PR02380A12, PR02529A15, PR02529A18 and PR02529A11. I will mention that we need the devices to be cleaned or they will be charged a fee. They have not taken any notice of this in the past and always pay that fee. Will ask for cert of decontamination and no batteries and SRS number on all paperwork
 15/Apr/2026 Kate Griffiths

update: ps sorry the above is on 2x it was not done intentionally and I have no idea why it happened... they require CALIBRATION ONLY and agree to pay cleaning fee if needed. Email attached. Items on their way...

20/Apr/2026 Robert Connor

Received 10 x V1000 s/n PR02380A12, PR02529A11, PR02529A14, PR02529A15, PR02529A17, PR02529A18, PR02529A20, PR02529A22, PR02540A13, PR02540A14, with 6 x grey cover, missing 2 battery doors.

Units have obviously not been cleaned since they were last serviced and need deep clean before testing.

Ready For quote

CG need 27.4.26

USD
DIST

Repair Complete Signed _____

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN38725	Foetal Simulator	1410000	PR02380A12	
SRN38726	Foetal Simulator	1410000	PR02529A11	
SRN38727	Foetal Simulator	1410000	PR02529A14	
SRN38728	Foetal Simulator	1410000	PR02529A15	
SRN38729	Foetal Simulator	1410000	PR02529A17	
SRN38730	Foetal Simulator	1410000	PR02529A18	
SRN38731	Foetal Simulator	1410000	PR02529A20	
SRN38732	Foetal Simulator	1410000	PR02529A22	
SRN38733	Foetal Simulator	1410000	PR02540A13	
SRN38734	Foetal Simulator	1410000	PR02540A14	

14800000 x 10
S/N's, SRS, SRN's
@ \$63.40 each

1430309 x 10
SRS, SRN's
FOC. \$16.90 each

1430320 x 7
SR SRS, SRN 68725

1430277 x 2
SRS, SRN \$9.40 each

1430288
SRS, SRN x 1 \$5.50

1440001 x 1 @ \$66.00

EXW: 36x36x25cm 5.50kg ←