

Service Repair Sheet 69412

Contact Name Tim Bray  
Company/ Hospital Name Medisafe Ltd  
Department Purchasing  
Position Purchase Contact  
Direct Phone 01962 885777  
General Phone 01962885777  
Opera Account 00011608  
Email tim.bray@medisafe.org.uk  
Order Number 6286  
Date Received 23/Apr/2026  
Booked in By Robert Connor

---

| Repair         | Ref     | S/N        | Equipment Type   |                                        |
|----------------|---------|------------|------------------|----------------------------------------|
| SRN38748       | 1410000 | PR03560A11 | Foetal Simulator | Complete - Repaired<br>Time :0 Hour(s) |
| Parts Replaced |         |            |                  |                                        |
|                |         | Qty: 1     | 1480000          |                                        |
|                |         | Qty: 1     | 1430309          |                                        |

V1000 has had transducer interface cushion replaced and calibration has been checked.

---