

Service Repair Sheet SRS69361

Contact Name: Koji Tateishi  
 Company/ Hospital Name: Ichinen Manufacturing Co., Ltd  
 Department:  
 Position:  
 Direct Phone:  
 General Phone: 00810358250418  
 Opera Account: 00007696  
 Email: tateishi@ichinen.co.jp  
 Order Number:  
 Date Received: 17/Mar/2026  
 Booked in By: Robert Connor  
 Main Company: Viamed  
 Type Return: Bring To Attention

Notes I'm experiencing problems with Teledyne oxygen sensors R17-AH and R22-AV. The sensors ending in "E5" are experiencing a symptom where the sensor output drops to zero within a year, making them unable to measure oxygen. I currently have seven of them. I'd like to return them and have them analyzed for the cause.

17/Mar/2026 Robert Connor  
 Returned 75 sensors.  
 17/Mar/2026 Robert Connor  
 44 x R22AHJR, 18 x R17AH, 9 x SOX-OXYS, 3 x SOX-OXY, 1 x R22AV with cracked case.  
 17/Mar/2026 Philip Crossley  
 After a quick test -  
 14 (out of 38) of 0110361 are faulty.  
 1 (of 1) 0110132 has split body.  
 3 (of 7) of 0110361 are faulty.  
 5 (of 18) of 0110137 are faulty.  
 10 (of 11) of Jitco sox-oxys are faulty.  
 24/Mar/2026 Philip Crossley  
 I have spoken to SN about this 24/Mar/2026 Catherine Spence  
 With Phil and Steve Nixon  
 08/Apr/2026 Philip Crossley  
 Steve has taken the whole repair  
 08/Apr/2026 Catherine Spence  
 Steve Speaking with staff at Jikco  
 08/Apr/2026 Catherine Spence  
 Test results to be entered into system  
 16/Apr/2026 Philip Crossley  
 Results added. 17/Apr/2026 Catherine Spence  
 with engineer  
 29/Apr/2026 Catherine Spence  
 with Steve and engineer  
 13/May/2026 Derek Lamb  
 Ichine have agreed to send the ok ones back, the other heading back to Teledyne.  
 16/May/2026 Catherine Spence  
 engineers room, Steve has given me the info for the return

0140011 x 27  
 (0110361)  
 SN's, SRS, SRN's  
 Value for Customs \$36.80

0140011 x 14  
 (0110137)  
 SN's SRS, SRN's  
 Value for Customs \$45.10.

0140016 x 1  
 (0110132)  
 SN, SRS, SRN return to  
 customer as requested  
 Value for Custom \$32.00

EXW x 1 FEDEX  
 A/C: 2680 93451

Ready For quote

Repair Complete Signed

CGNEON 26.5.26.

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN38593	Oxygen Sensor	0110361	A257909	Yes
SRN38594	Oxygen Sensor	0110361	A257912	Yes

The non highlighted S/N numbers are being returned to supplier