

Service Repair Sheet 69361

Contact Name Koji Tateishi
Company/ Hospital Name Ichinen Manufacturing Co., Ltd
General Phone 00810358250418
Opera Account 00007696
Email tateishi@ichinen.co.jp
Date Received 17/Mar/2026
Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38593	0110361	A257909	Oxygen Sensor	
				Time :0 Hour(s)

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38594	0110361	A257912	Oxygen Sensor	
				No Fault Found Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38595	0110361	A257901	Oxygen Sensor	
				No Fault Found Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38596	0110361	A257871	Oxygen Sensor	
				No Fault Found Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38597	0110361	A257888	Oxygen Sensor	
				No Fault Found Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38598	0110361	A257870	Oxygen Sensor	
				No Fault Found Time :0 Hour(s)

No fault found.

Service Repair Sheet 69361

Contact Name Koji Tateishi
Company/ Hospital Name Ichinen Manufacturing Co., Ltd
General Phone 00810358250418
Opera Account 00007696
Email tateishi@ichinen.co.jp
Date Received 17/Mar/2026
Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38599	0110361	A257868	Oxygen Sensor	
				Time :0 Hour(s)

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38600	0110361	A257890	Oxygen Sensor	
				No Fault Found
				Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38601	0110361	A257830	Oxygen Sensor	
				No Fault Found
				Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38602	0110361	A257863	Oxygen Sensor	
				Time :0 Hour(s)

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38603	0110361	A257820	Oxygen Sensor	
				No Fault Found
				Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38604	0110361	A257854	Oxygen Sensor	
				Time :0 Hour(s)

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38605	0110361	A257904	Oxygen Sensor	
				Time :0 Hour(s)

Service Repair Sheet 69361

Contact Name Koji Tateishi
Company/ Hospital Name Ichinen Manufacturing Co., Ltd
General Phone 00810358250418
Opera Account 00007696
Email tateishi@ichinen.co.jp
Date Received 17/Mar/2026
Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38606	0110361	A257842	Oxygen Sensor	No Fault Found Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38607	0110361	A257812	Oxygen Sensor	No Fault Found Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38608	0110361	A257837	Oxygen Sensor	No Fault Found Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38609	0110361	A257803	Oxygen Sensor	No Fault Found Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38610	0110361	A257880	Oxygen Sensor	No Fault Found Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38611	0110361	A257846	Oxygen Sensor	No Fault Found Time :0 Hour(s)

No fault found.

Service Repair Sheet 69361

Contact Name Koji Tateishi
Company/ Hospital Name Ichinen Manufacturing Co., Ltd
General Phone 00810358250418
Opera Account 00007696
Email tateishi@ichinen.co.jp
Date Received 17/Mar/2026
Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38612	0110361	A257859	Oxygen Sensor	
				Time :0 Hour(s)

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38613	0110361	A257838	Oxygen Sensor	
				Time :0 Hour(s)

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38614	0110361	A257896	Oxygen Sensor	
				Time :0 Hour(s)

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38615	0110361	A257864	Oxygen Sensor	
				No Fault Found
				Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38616	0110361	A257849	Oxygen Sensor	
				Time :0 Hour(s)

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38617	0110361	A257826	Oxygen Sensor	
				No Fault Found
				Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38618	0110361	A257833	Oxygen Sensor	
				Time :0 Hour(s)

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38619	0110361	A257878	Oxygen Sensor	
				Time :0 Hour(s)

Service Repair Sheet 69361

Contact Name Koji Tateishi
Company/ Hospital Name Ichinen Manufacturing Co., Ltd
General Phone 00810358250418
Opera Account 00007696
Email tateishi@ichinen.co.jp
Date Received 17/Mar/2026
Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38620	0110361	A257892	Oxygen Sensor	
				Time :0 Hour(s)

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38621	0110361	A257882	Oxygen Sensor	
				No Fault Found Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38622	0110361	A257865	Oxygen Sensor	
				No Fault Found Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38623	0110361	A257893	Oxygen Sensor	
				Time :0 Hour(s)

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38624	0110361	A257915	Oxygen Sensor	
				No Fault Found Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38625	0110361	A257917	Oxygen Sensor	
				No Fault Found Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38626	0110361	A257855	Oxygen Sensor	
				No Fault Found Time :0 Hour(s)

No fault found.

Service Repair Sheet 69361

Contact Name Koji Tateishi
Company/ Hospital Name Ichinen Manufacturing Co., Ltd
General Phone 00810358250418
Opera Account 00007696
Email tateishi@ichinen.co.jp
Date Received 17/Mar/2026
Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38627	0110361	A257869	Oxygen Sensor	No Fault Found Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38628	0110361	A257853	Oxygen Sensor	Time :0 Hour(s)

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38629	0110361	A257789	Oxygen Sensor	Time :0 Hour(s)

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38630	0110361	A257848	Oxygen Sensor	No Fault Found Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38631	0110132	287898	Oxygen Sensor	Return Unrepaired Time :0 Hour(s)

Return to customer

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38632	0110361	A260231	Oxygen Sensor	Time :0 Hour(s)

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38633	0110361	A257807	Oxygen Sensor	Time :0 Hour(s)

Service Repair Sheet 69361

Contact Name Koji Tateishi
Company/ Hospital Name Ichinen Manufacturing Co., Ltd
General Phone 00810358250418
Opera Account 00007696
Email tateishi@ichinen.co.jp
Date Received 17/Mar/2026
Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38634	0110361	A257895	Oxygen Sensor	No Fault Found Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38635	0110361	A260193	Oxygen Sensor	No Fault Found Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38636	0110361	A260213	Oxygen Sensor	No Fault Found Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38638	0110361	A260240	Oxygen Sensor	No Fault Found Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38639	0110137	244777	Oxygen Sensor	No Fault Found Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38640	0110137	244779	Oxygen Sensor	No Fault Found Time :0 Hour(s)

No fault found.

Service Repair Sheet 69361

Contact Name

Koji Tateishi

Company/ Hospital Name

Ichinen Manufacturing Co., Ltd

General Phone

00810358250418

Opera Account

00007696

Email

tateishi@ichinen.co.jp

Date Received

17/Mar/2026

Booked in By

Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38641	0110137	206594	Oxygen Sensor	No Fault Found Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38642	0110137	244781	Oxygen Sensor	No Fault Found Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38643	0110137	244783	Oxygen Sensor	No Fault Found Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38644	0110137	260035	Oxygen Sensor	Time :0 Hour(s)

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38645	0110137	260057	Oxygen Sensor	Time :0 Hour(s)

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38646	0110137	260042	Oxygen Sensor	No Fault Found Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38647	0110137	220670	Oxygen Sensor	No Fault Found Time :0 Hour(s)

No fault found.

Service Repair Sheet 69361

Contact Name

Koji Tateishi

Company/ Hospital Name

Ichinen Manufacturing Co., Ltd

General Phone

00810358250418

Opera Account

00007696

Email

tateishi@ichinen.co.jp

Date Received

17/Mar/2026

Booked in By

Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38648	0110137	260091	Oxygen Sensor	
				Time :0 Hour(s)

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38649	0110137	260063	Oxygen Sensor	
				No Fault Found
				Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38650	0110137	244778	Oxygen Sensor	
				No Fault Found
				Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38651	0110137	220671	Oxygen Sensor	
				No Fault Found
				Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38652	0110137	244780	Oxygen Sensor	
				No Fault Found
				Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38653	0110137	260009	Oxygen Sensor	
				Time :0 Hour(s)

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38654	0110137	260092	Oxygen Sensor	
				Time :0 Hour(s)

Service Repair Sheet 69361

Contact Name Koji Tateishi
Company/ Hospital Name Ichinen Manufacturing Co., Ltd
General Phone 00810358250418
Opera Account 00007696
Email tateishi@ichinen.co.jp
Date Received 17/Mar/2026
Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38655	0110137	220672	Oxygen Sensor	No Fault Found Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38656	0110137	220669	Oxygen Sensor	No Fault Found Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38708	0110132	243149	Oxygen Sensor	Time :0 Hour(s)

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38709	0110132	257463	Oxygen Sensor	Time :0 Hour(s)

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38710	0110132	257565	Oxygen Sensor	Time :0 Hour(s)

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38711	0110137	259991	Oxygen Sensor	Time :0 Hour(s)

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38712	0110137	259995	Oxygen Sensor	Time :0 Hour(s)

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38713	0110137	260014	Oxygen Sensor	Time :0 Hour(s)

Service Repair Sheet 69361

Contact Name Koji Tateishi
Company/ Hospital Name Ichinen Manufacturing Co., Ltd
General Phone 00810358250418
Opera Account 00007696
Email tateishi@ichinen.co.jp
Date Received 17/Mar/2026
Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38714	0110137	260015	Oxygen Sensor	
				Time :0 Hour(s)

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38715	0110137	260037	Oxygen Sensor	
				Time :0 Hour(s)

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38716	0110137	260038	Oxygen Sensor	
				Time :0 Hour(s)

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38717	0110137	260074	Oxygen Sensor	
				Time :0 Hour(s)

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38718	0110137	260093	Oxygen Sensor	
				Time :0 Hour(s)

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38719	0110137	260013	Oxygen Sensor	
				No Fault Found
				Time :0 Hour(s)

No fault found.
