

Service Repair Sheet 69419

Contact Name	Sudath Weeraman
Company/ Hospital Name	Prime Lanka Associate
Direct Phone	9410718732285
Opera Account	00006714
Email	sudathweeraman17@gmail.com
Date Received	26/May/2026
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38799	0110429	LH45899010	Oxygen Sensor	
				Time :0 Hour(s)

Parts Replaced
Qty: 1 0110429

Replaced under warranty with S/N MC97299061.
