

Service Repair Sheet 69423
Contact Name Don Macdonald
Company/ Hospital Name Stornoway Subsea
Direct Phone 07880892936
General Phone 07880892936
Opera Account CID17142
Email donmacdonald21@hotmail.com
Date Received 07/May/2026
Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38764	7910201	TX5662	Vandagraph Tek Ox	Complete - Repaired Time :0 Hour(s)

The Tek-Ox analyser has been repaired under warranty. The PCB has been replaced.
