

Service Repair Sheet 69418

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

David Edmondson

Royal Preston Hospital

Medical Engineering

Technician

01772524598

01772716565

00004260

david.edmondson@lthtr.nhs.uk

TP38873

19/May/2026

Robert Connor

---

| Repair   | Ref     | S/N    | Equipment Type | Complete - Repaired |
|----------|---------|--------|----------------|---------------------|
| SRN38795 | 0310030 | VMEF03 | Tom Thumb      | Time :0 Hour(s)     |

Parts Replaced

Qty: 1 0380000

Tom Thumb TT480 VMEF03 has been stripped and cleaned then reassembled with new O rings. The two valves have been checked and reset before QA.

---

| Repair   | Ref     | S/N    | Equipment Type | Complete - Repaired |
|----------|---------|--------|----------------|---------------------|
| SRN38796 | 0310030 | VMEF08 | Tom Thumb      | Time :0 Hour(s)     |

Parts Replaced

Qty: 1 0380000

Tom Thumb TT480 VMEF08 has been stripped and cleaned then reassembled with new O rings. The two valves have been checked and reset before QA.

---

| Repair   | Ref     | S/N      | Equipment Type | Complete - Repaired |
|----------|---------|----------|----------------|---------------------|
| SRN38797 | 0310200 | B1551983 | Blender        | Time :0 Hour(s)     |

Parts Replaced

Qty: 1 0380020

Qty: 1 0332000 - included in service FOC cg 9-6-26

Blender B1551983 has had an annual service with new gas filters and the calibration has been checked.

---

| Repair   | Ref     | S/N      | Equipment Type | Complete - Repaired |
|----------|---------|----------|----------------|---------------------|
| SRN38798 | 0310200 | B1551984 | Blender        | Time :0 Hour(s)     |

Parts Replaced

Qty: 1 0380020

Qty: 1 0332000 - included in service FOC cg 9-8-26

Blender B1551984 has had an annual service with new gas filters and the calibration has been checked.

OBI 0104  
low suction  
controller filter