

Service Repair Sheet 69439

|                        |                   |
|------------------------|-------------------|
| Contact Name           | Rob Pochwyt       |
| Company/ Hospital Name | Bar O2 Limited    |
| General Phone          | 01785338133       |
| Opera Account          | CID11243          |
| Email                  | support@baro2.com |
| Date Received          | 03/Jun/2026       |
| Booked in By           | Robert Connor     |

---

|                |         |            |                 |                             |
|----------------|---------|------------|-----------------|-----------------------------|
| Repair         | Ref     | S/N        | Equipment Type  | Under Warranty              |
| SRN38804       | 0111265 | KA21311017 | Oxygen Analyser |                             |
| Parts Replaced |         |            |                 | Replaced<br>Time :0 Hour(s) |

Qty: 1    0111265

Replaced under warranty with S/N LJ05211008.

---

|                |         |            |                 |                             |
|----------------|---------|------------|-----------------|-----------------------------|
| Repair         | Ref     | S/N        | Equipment Type  | Under Warranty              |
| SRN38805       | 0111265 | KA21311020 | Oxygen Analyser |                             |
| Parts Replaced |         |            |                 | Replaced<br>Time :0 Hour(s) |

Qty: 1    0111265

Replaced under warranty with S/N LJ05211013.

---